

The review of a few of the accidents listed below is presented on <a href="https://www.avioconsult.com/accidents.htm">https://www.avioconsult.com/accidents.htm</a>. For preventing such accidents: <a href="https://www.avioconsult.com/downloads.htm">https://www.avioconsult.com/downloads.htm</a>.

No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
Accide	ents are not includ	ed in this list if some kind of report	is not (yet) publish	ned on the Internet. It ma	ay take up to t	wo years before any	y preliminary or full report is made available.
1	2025-04-25	DHC-6-400 Twin Otter	Thailand	Off Hua Hin Apt	6/6	ASN	No. 2 engine failed shortly after takeoff; aircraft spun down into sea
2	2025-02-16	Douglas A-20G Havoc	USA	Laredo, TX	0/1	ASN	R-engine failure, prop. not feathered, impacted short of runway, fire
3	2024-12-11	PA-32-350 Navajo Chieftain	USA	Victoria, TX	0/1	B3A	Engine trouble during return, attempted emergency landing - crashed
4	2024-02-01	Grumman GA-7 Cougar	USA	·	1/1	ASN	?
5	2023-11-10	Cessna 421C	AUS	Sunshine Coast	0/2	B3A	Engine failure during cruise FL 120, unable to reach airport. Ditched.
6	2023-09-09	Antonov 26	Mali	Gao, Gao	10/10	B3A	Technical problems with an engine, crashed
7	2023-08-13	Rockwell Cdr 500	USA	Key West, FL	0/1	B3A	Engine failure en-route, ditched
8	2023-03-17	Beech 58P	USA	Lubbock, TX	1/1	CEN23FA139	Fuel starvation left engine, lost control, impacted the ground
9	2023-02-22	Diamond DA42	Slovakia	Trencianske Stan.	4/4	ASM	Probably during engine out training
10	2023-01-18	Cessna 414	USA	Modesto Apt	1/1	ASN	Engine problems after takeoff, crashed during return to airport
11	2023-01-18	Piper PA-31-350	USA	Geauga Apt	0/6	ASN	Loss of engine power, tried emergency landing, overran runway
12	2022-11-21	Piper PA-31-350	Colombia	Medellín	8/8	B3A	After takeoff, engine problems. Loss of control.
13	2022-10-03	Britten-Norman BN-2	Australia	Plain, Valley	0/7	B3A	One engine shut down en-route, attempted emer. landing, crashed
14	2022-09-15	Swearingen SA227 Metro III	Mexico	Saltillo, Coahuila	0/2	B3A	After takeoff, engine #2 lost power. Attempt emer landing, crashed
15	2022-07-16	Antonov 12	Greece	Kavala	8/8	ASN	Crew reported engine failure at 21,000 ft over sea, crashed on land
16	2022-06-24	Ilyushin II-76MD	Russia	Ryazan-Dyagilevo	5/?	ASN	Fire #4 shortly after takeoff, crash landed in a field
17	2022-05-20	EMB-110P1	Brazil	Eldorado do Sul	0/2	ASN	Left engine malfunctioned while on final approach
18	2022-03-05	Dornier 228-101	India	Kanpur AF Station	0/4	ASN	Landed with failed engine #1, veered off the runway to the right
19	2022-02-16	Beech 58 Baron	USA	Davidson Cnt Apt	1/1	ASN	After takeoff, engine failure. Crashed.
20	2022-01-19	Beech 58 Baron	Brazil	Bacacheri Apt	0/3	ASN	One engine failed at 7000ft, could not maintain alt., landed off-rwy
21	2022-01-05	Cessna 402	Bahamas	Chub Cay	0/2	B3A	Pilot reported engine problems on approach. Ditched.
22	2021-12-10	Swearingen SA-226AT	USA	Reg. Airport, NH	1/1	ASN	Pilot reported an engine failure on final. Crashed 600m short of rwy.
23	2021-10-19	Cessna 401	Mexico	Tapachula Chiapas	1/1	B3A	Shortly after takeoff, pilot reported engine problem. LOC, crashed
24	2021-10-10	Let L-410UVP-E3	Russia	Menzelinsk	16/22	ASN	Shortly after takeoff, pilot reported failure of #1 engine. Crashed.
25	2021-09-29	Beech B58 Baron	Brazil	Vilhena-Rondônia	0/2	ASN	En route, power loss right engine. Emergency landing, subst. damage
26	2021-07-15	Piper PA-23	USA	Easton, MD	0/2	ERA21LA289	During training, left engine failed, landed in corn field
27	2021-06-19	Let L-410	Russia	Tanay	4/19	B3A	Right engine believed to have failed shortly after takeoff. Crashed
28	2021-06-08	Cessna 310Q	Brazil	Rondonópolis, MT	4/4	ASN	Engine failed 30 min. after takeoff. Crashed during forced landing
29	2021-06-19	Let L-410	Russia	Tanay	4/19	B3A	Shortly after takeoff, the right engine suffered power loss. Crashed
30	2021-05-06	Aerostar 600	USA	La Belle, FL	1/2	ERA21FA212	Following a crash, the right propeller was found feathered
31	2021-03-02	Let L-410UVP-E	South Sudan	Pieri Airstrip	10/10	ASN	One engine failed 10 min. after takeoff, the 2 <sup>nd</sup> while RTB
32	2021-02-21	Beech 300 King Air 350	Nigeria	Abuja-Nnamdi Azi	7/7	ASN	Loss of engine power shortly after takeoff - crashed
33	2021-01-10	Cessna 421B	USA	Farmingdale-Rep.	0/1	B3A	Engine failure after takeoff, lost control, crashed while RTB 3km
34	2021-01-04	Beech G58	USA	Credit, Arkansas	2/2	CEN21LA107	In-flight, loss thrust left engine, inadv. collision with transmission lines
35	2020-12-01	DHC-6-300 Twin Otter	P.N. Guinea	Wobagen Airstrip	0/	ASN	Asymmetrical power from initiating takeoff run, vacated the airstrip
36	2020-10-22	Cessna 310R	USA	Las Vegas, NV	2/2	ASN	Pilot informed ATC one engine shut down 5 min prior to crash
37	2020-09-25	Antonov 26Sh	Ukraine	Chuhuiv AB	26/27	ASN	After takeoff, pressure drop Torque #1, crashed on final approach
38	2020-08-20	Beech 200 Super King Air	USA	Chicago/Rockford	1/1	CEN20LA352	Reduction of thrust left engine during takeoff. Crashed
39	2020-07-01	Cessna 320	USA	Round Rock, TX	1/1	CEN20LA256	Flames observed left engine, airplane sputtering, crashed
40	2020-05-12	Piper PA-34	USA	Hollywood, FL	1/2	ERA20LA177	Right engine failed in-flight, unable to maintain alt., emer landing

1) Sources: NTSB, ATSB, TAIC, Aviation-Safety.Net (ASN), Flight Safety Foundation (FSF), Plane Crash Info (PCI), Airdisaster.com (AD), etc. 1 Updated: 2025-04-29; Avio Consult (.com)



42			Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
	2020-04-01	Diamond DA42	USA	Palm Coast, FL	0/2	ERA20CA143	Practicing SE approach, drifted, initiated GA, drifted, ground impact
	2020-03-21	Cessna 310	USA	Charleston,SC	1/1	ERA20LA132	Pilot reported engine problems en route, left first then both; crashed
43	2020-02-20	Piper PA-60 Aerostar	Spain	Pamplona	1/1	BAAA	Engine problems on approach, crashed 500m from airfield
44	2020-01-16	Beech 76	USA	St. Charles, MI	0/2	CEN20CA062	Selected full power on operating engine during OEI training approach
45	2019-10-18	Douglas DC-3	Bahamas	Nassau-Lynden	0/2	BAAA	On final, left engine failed, ditched 2.5 nm short of runway 14
46	2019-10-05	Piper Aerostar 602P	USA	Kokomo, IN	1/1	CEN20FA002	Engine failure due to wrong fuel, crashed after takeoff
	2019-10-02	Boeing B-17	USA	Windsor Locks, CT	7/14	ERA20MA001	After takeoff #4 failed, crashed on final following right hand pattern
48	2019-10-01	Beech 55	USA	Grove City, PA	0/1	ERA20LA052	On approach, #1 failed due to low fuel, landed left of runway
49	2019-08-18	Beech 95B55	USA	Wilmington, Delaw	2/2	ERA19FA250	Fuel starvation left engine, lost control during approach
	2019-06-30	Beech B300 KA 350i	USA	Dallas-Addison Apt	10/10	CEN19MA190	Left engine failure after liftoff, LOC, crashed in hangar
	2019-06-10	Cessna 425	USA	Butler, MO	1/1	CEN19FA161	Reported R. engine problem during descent; shut down, lost control
	2019-05-05	Beech A60	USA	Santa Rosa, NM	2/2	ANC19FA018	Loss of control during approach while the left engine was shut down
	2019-05-03	DC-3	CA	Hay River/MC Apt	0/2	A19W0052	Shortly after takeoff, left engine failed, could not make it to the rwy
	2019-04-22	Beech 58	USA	Kerrville, TX	6/6	CEN19FA124	Asym thrust during approach, prop not feathered, crashed
	2019-03-19	Beech D50	USA	Riverside, CA	1/1	ASN	Impacted terrain after engine failure; no prop. feathering possible
	2019-03-09	Douglas DC-3	Colombia	San Martin	14/14	ASN	Crashed after reporting engine #1 problems
	2019-03-08	Piper PA-23	USA	Pahokee, FL	5/	WPR19FA093	Left eng. failed. Loss of control during maneuvering for landing
	2019-02-08	Convair C131	Atlantic Oce'n	Atlantic Ocean	1/2	ERA19LA096	Problems left engine prop control. Continued. Then right eng surged
	2019-01-21	Douglas DC-3C	USA	Kidron, OH	2/2	CEN19LA056	Just after liftoff, #1 lost total power, autofeather incomplete. Crashed
	2018-12-01	Cessna 335	USA	Ft. Lauderdale	2/3	ERA19FA060	Shortly after takeoff, loss of power left engine. Crashed on approach
	2018-09-05	Cessna 340A	USA	Port Huron, MI	1/1	CEN18FA371	Engine failure during approach, crashed during re-shoot approach
	2018-08-09	Beech G58 Baron	GE	Muenster	2/2	BFU18-1170-3X	
	2018-08-01	Piper PA-31	CA	Calgary/Spr Apt	2/2	A18W0116	Asym. power, V <vmca, controlled="" crashed<="" departed="" flight,="" spin,="" td=""></vmca,>
	2018-07-30	Piper PA-60 Aerostar	USA	Greenville, Maine	3/3	BAAA	Pilot reported engine problems, loss of power on final, crashed
	2018-07-20	Piper PA-61 Aerostar	USA	Baton Rouge	0/1	BAAA	Loss of engine power after takeoff; hard landing in grassy field
	2018-07-10	Convair CV-340	South Africa	Pretoria	2+1/19	BAAA	Shortly after takeoff, smoke left engine. Loss of control on approach
	2018-07-07	Piper PA-34	USA	Gulf Shores, AL	0/5	ERA18LA186	After takeoff, left engine lost power, landed in trees. Fuel shortage.
	2018-06-30	BN-2A-26 Islander	Belize	San Pedro Apt	0/8	ASN	Forced landing after loss of engine power
	2018-06-26	Cessna 414	UK	Oxfordshire	0/2	AAIB bul. 4/ '19	Shortly after takeoff, right engine stopped. Crashed
	2018-06-01	Beech 76	Australia	Cessnock, NSW		AO-2018-047	Right engine lost power during descent. Subst damage forced landing
	2018-05-02	Lockheed WC-130H	USA	Savannah, GA	9/9	Aerossurance	Crashed shortly after takeoff after failure engine #1
	2018-04-26	Cessna 402B	USA	New Braintree, MA	0/3	ASN	Following engine failure, force landed on cart path where it crashed
	2018-03-31	Cessna 421C	Canada	Kingston	0/3	ASN	Engine problem reported, landed short of runway
	2018-03-29	Swearingen SA-227 DC	Bolivia	Riberalta	0/14	ASN	Bird hits during takeoff run, aborted, overran runway
	2018-03-08	Piper PA-31-310 Navajo	USA	Laredo, TX	2/2	BAAA	Shortly after takeoff problems reported, LOC crashed, feathered prop
	2018-03-01	Beech 60 Duke	USA	Ferris, TX	0/1	BAAA	Engine problems en-route, emerg landing, prop #2 feathered?
	2017-12-10	Aerostar 601	USA	Miami, FL	1/1	CEN18FA050	LOC shortly after takeoff. NTSB Safety Alert 81.
	2017-12-07	Beech BE-58	USA	St. Croix, USVI	5/5	ERA18FA046	Takeoff, engine problems, crashed, left prop appeared feathered
	2017-02-21	Beech 200 King Air	Australia	Essendon Airport	5/5	AO-2017-024	On liftoff, airplane yawed to left and crashed in building. Eng out?
	2017-10-28	Cessna 310R	Australia	Port Macquarie	2/2	AO-2017-105	On approach, airplane rolled left and crashed. No thrust left engine.
	2017-10-12	Embraer 120	Angola	Cuilo	7/7	BAAA	15 min. after takeoff, one engine on fire, crashed
	2017-09-10	Antonov AN-26	DR Congo	Goma	4/0	BAAA	Engine problems after takeoff, landed long, overran runway
	2017-08-16	Let 410UVP	Honduras	Comayagua	1/3	BAAA	Crashed in building, photo shows right propeller feathered



No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
84	2017-07-13	Piper PA-31 T	USA	Tyler, TX	2/2	CEN17FA266	Loss of engine #2 power shortly after takeoff and subsequent LOC
85	2017-06-30	Cessna 310R	USA	Santa Ana, CA	0/2	WPR17LA136	Loss of right engine power shortly after departure
86	2017-06-03	Piper PA-23	Puerto Rico	San Juan	1/3	ERA17FA195	Shortly after takeoff, pilot reported an engine failure. Impacted water
87	2017-05-31	Cessna 421A	Argentina	Buenos Aires	0/3	BAAA	On approach, an engine failed. Crashed during emergency landing
88	2017-05-30	Antonov AN-26	Russia	Balashov	1/6	BAAA	During training, on approach engine failure, loss of control
89	2017-05-31	Cessna 421	Argentina	El Palomar	0/3	BAAA	On approach, an engine failed. Crashed 9 nm short of runway.
90	2017-04-25	Cessna 421C	USA	Huntsville, TX	1/1	BAAA	Engine problems en route. Crashed while on approach 4 nm short
91	2016-12-13	Beech 200	2017-02-21	Moomba Apt	0/?	AO-2016-170	Left engine fire warning, shut down, not feathered, landed left of rwy
92	2016-12-07	ATR-42-500	Pakistan	Havelian	47/47	BAAA	During cruise, left engine failed. Loss of Control - crashed
93	2016-11-18	Piper PA-31 T	Elko, NV		4/4	WPR17FA024	Loss left engine power during initial climb, banked left, crashed
94	2016-08-14	Piper PA-31-310 Navajo	USA	Tuscaloosa	6/6	BAAA	Pilot reported engine problems on approach, stalled and crashed
95	2016-07-31	Embraer EMB-820 Navajo	Brazil	Londrina	8/8	BAAA	On approach, engine failure (acc to locals), stalled and crashed
96	2016-06-26	Canadair CL-215	Greece	Dervenochoria	0/2	BAAA	En route, left engine caught fire. Crashed during emergency landing
97	2016-05-23	Piper PA-23	USA	Lakeland, FL	2/2	ERA15FA109	Likely caused by asymmetrical power during instructional flight
98	2016-05-18	Antonov AN-12B	Afghanistan	Camp Dwyer	7/9	BAAA-ACRO	Lost height after engine failure on departure, impacted with terrain
99	2016-05-05	Cessna 310F	USA	North Little Rock	1/2	CEN16FA172	Left engine failed shortly after takeoff, crashed during return to land
100	2016-04-26	Cessna 421B	USA	Foley, Alabama	0/1	BAAA-ACRO	During initial climb, one engine sputtered, crashed
101	2016-04-13	BN-2T Islander	Papua Nw G	Kiungua Airport	12/12	ASN	Impacted terrain short of runway, prop #2was found feathered.
102	2016-04-09	Rockwell Grand Cdr 690	USA	Hare, TX	2/2	BAAA-ACRO	Engine problems en route, LOC and crashed
103	2016-04-07	Douglas DC-3	Colombia	Puerto Guitán	0/3	ERA16WA155	Forced landing due to loss of power on the left engine, initial climb
104	2016-03-18	Beech 1900D	Pakistan	Karachi	0/21	ASN	Crash landed after takeoff after one engine failed
105	2016-03-10	Piper PA-34-220T	Germany	Osnabrueck	0/4	BFU16-0238-3X	Left engine failure after takeoff, Loss of alt., emer landing
106	2016-03-09	Antonov 26B	Bangladesh	Cox's Bazar Apt	3/4	ASN	Shortly after takeoff, left engine failure. Crashed while RTB
107	2016-02-16	Casa CN-235	Malaysia	Kuala Selangor	0/8	BAAA-ACRO	10 min after takeoff, left engine failed, crash landed into the sea
108	2015-11-06	Cessna 310R	Australia	Mildura airport	1/1	AO-2015-129	On approach, left engine inop, right engine high power, control lost
109	2015-10-26	Piper PA-31	USA	Weston, FL	1/3	ERA16LA026	Forced landing with left props feathered
110	2015-10-14	Cessna 421B	USA	Hammond, LA	2/2	CEN16A013	Loss of power right engine shortly after takeoff. Crashed.
111	2015-08-09	Cessna 421B	USA	Clovis, NM	0/1	CEN15LA354	Loss left engine power during final approach, impacted terrain.
112	2015-07-31	CASA CN-235M-200	Colombia	Codazzi	11/11	ASN	Pilot reported engine failure prior to the accident.
113	2015-07-27	Embraer EMB-110	Brazil	Lagoa Santa AB	0?	ASN	During touch & go; photo showed left propeller feathered, veered off
114	2015-07-18	Cessna T310R	USA	Cody, WY	4/4	CEN15FA307	LOC due to loss power left engine, crashed
115	2015-06-30	C-130B Hercules	Indonesia	MES AFB	122/122	ASN	Engine #4 failed on takeoff. Impacted an antenna due to low ROC.
116	2015-05-09	A400M	Spain	Sevilla	4/6	ASN	Multiple engines failed due to software problems, crashed.
117	2015-02-14	Cessna 310C	Serbia	Zrenjanin Airport	2/2	ASN	Crashed during engine-out training.
118	2015-02-11	Beech 1900	USA	Miami	4/4	ASN	2 sec after rotation, left propeller feathered uncommanded, crashed
119	2015-02-04	ATR 72-600	Taiwan	Taipei	43/58	ASN	After takeoff, left engine failed. Closed wrong throttle, LOC, crashed.
120	2015-01-02	Piper PA 34-200T	USA	Kuttawa, KY	4/5	ERA15FA088	During cruise, right engine failure, crashed.
121	2014-12-30	Cessna 404	USA	Englewood, CO	1/1	CEN15FA090	Lost engine, crashed during returning to takeoff airport.
122	2014-12-02	Piper PA-31-350	Bahamas	New Providence	1/11	A14-005585	Following land gear problems, Right engine failure, ditched.
123	2014-11-18	Aero Commander 500B	USA	Chicago, II	1/1	CEN15FA048	After takeoff, left engine trouble, LOC on final approach
124	2014-11-17	Cessna 401A	USA	Fulton, MO	0/3	CEN15LA050	Engine failure after liftoff, takeoff aborted, overran the runway.
125	2014-10-30	Beechcraft B200 King Air	USA	Wichita	1+3/1	CEN15FA034	Engine failure on takeoff, crashed into FlightSafety building
126	2014-10-21	Beech D95A	USA	Bahama, NC	1/2	ERA15FA023	Engine failure training; crashed.



No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
127	2014-08-27	Cessna 310K	USA	El Dorado	0/2	CEN14LA461	Following touch&go, left eng. lost power, forced landing.
128	2014-08-10	HESA IrAn-140-100	Iran	Tehran	39/48	ASN	After takeoff, right engine failed; also overloaded; crashed.
129	2014-07-17	Piper PA-30	USA	Othello, WA	0/4	WPR14LA298	After TO, left engine rpm dropped, yaw to left and ground impact.
130	2014-07-05	Piper PA-31P-350	Poland	Częstochowa	11/12	BAAA-ACRO	Shortly after takeoff, no ROC, sputtering engine, crashed
131	2014-07-06	BN-2A Islander	Zambia	Chirundu	0/2	BAAA-ACRO	Engine problems en route; destroyed during emergency landing
132	2014-07-14	Fokker 50	Kenya	Nairobi	4/4	ASN	Left engine problems during takeoff run, continued, crashed
133	2014-07-02	Piper PA-30	USA	Harrison, AR	0/1	CEN14FA337	Immediately after takeoff left engine lost power, loss of control
134	2014-06-26	Cessna 414	USA	Maryland Hts, MI	0/1	CEN14LA324	During takeoff, left cargo door opened, left engine inop, crashed
135	2014-06-25	Piper PA-30	USA	Kalispell, MT	0/2	WPR14LA269	Right engine failure during takeoff, collided with terrain.
136	2014-06-18	IAI 1124A Westwind II	USA	Huntsville, AL	3/3	ASN	LOC on TO after TR #2 deployment
137	2014-06-02	Beech B200 Super King Air	Colombia	Bahía Solano-José	0/3	ASN	Loss of engine power after takeoff.
138	2014-05-27	Beech B200 Super King Air	Uruguay	Carmelo	5/9	ASN	Crash landing following pilot reporting engine trouble.
139	2014-02-21	Antonov 26	Tunesia	Grombalia	11/11	ASN	Pilot had reported engine problems to ATC.
140	2014-01-20	BN-2A-27 Islander	Romania	Pertreasa	2/7	ASN	Emergency landing after problem with engines.
141	2014-01-20	Antonov 28	Ethiopia	Addis Ababa	0/2	ASN	Engine problem, crashed during emergency approach.
142	2013-11-15	Cessna 310Q	UK	Hawarden, Chester	1/1	AAIB: 11/2014	Engine failure during go-around due to fuel starvation left engine.
143	2013-11-10	SA227-AC Metro III	Canada	Red Lake, Ont.	5/7	A13C0150	Loss of engine power on approach, Loss of control, crashed.
144	2013-11-10	MU-2B-25	USA	Owasso, OK	1	CEN14FA046	On approach, left engine failure, cont'd left turn, crashed.
145	2013-10-03	Embraer EMB-120	Nigeria	Lagos	14/20	ASN	Right engine failed during takeoff, crashed shortly after liftoff.
146	2013-09-11	Piper PA-34-200	Philippines	Barrio Laoac	0/4	RP-C1034	Pilot switched off RH magneto rather than fuel boost pump, crashed
147	2013-08-27	Cessna 421C	USA	Paris, IL	1/1	CEN13FA509	Failure to abirt takeoff with known problem left engine
148	2013-08-19	DC-3	Canada	Yellowknife NW	0/24	TSB CA	R engine fire after takeoff, low alt R turn, gear up landing S of rwy.
149	2013-08-03	Beech D55	USA	Conway, SC	3/3	ERA13FA348	Total loss of right engine due to fuel starvation, crashed
150	2013-08-03	Beech 58	Brazil	Jundiai Mun.	4/4	ERA13WA376	After takeoff smoke left engine, RTB, crashed (engine failure?)
151	2013-06-07	Piper PA-34	Brazil	Envira	1/6	ERA13WA306	Right engine failure after takeoff, ditched in river.
152	2013-03-29	Beech G58	NZ	Kawhia Harbour	2/2	WPR13WA177	Ditched in ocean, pilot reported loss of engine power.
153	2013-03-15	Piper PA-31T	USA	Fort Lauderdale, FL	3/3	ERA13FA168	Shortly after takeoff, right engine failure; crashed.
154	2012-12-08	Cessna 421C	USA	Lake Worth, FL	1/1	ERA13FA082	Loss of control after takeoff, left prop found feathered.
155	2012-11-21	Antonov An-26	Yemen	Saná	10/10	PCI	Crashed during emergency landing after en engine failed.
156	2012-11-04	Cessna 310	USA	Stotts City, MO	2/2	CEN13FA044	Shutdown engine in-flight, lost altitude, crashed.
157	2012-10-15	PA-34-200	Canada	Victoriaville, Q'bec	0/2	A12Q0182	Right engine lost power, emergency landing. Severe injuries & burns
158	2012-10-07	BN2A-26 Islander	Antigua	VC Bird Int Apt	3/4	AAIB S4/2013	Crashed shortly after takeoff, water in fuel RH engine - lost power
159	2012-10-07	Antonov 12BP	Sudan	Khartoum	15/22	FSF	Engine problems en-route, crashed during emergency landing
160	2012-09-28	Dornier DO-228	Nepal	Kathmandou	19/19	SKYbrary	Early rotation, left engine reduced rpm after takeoff, +birdhit, V <vmc< td=""></vmc<>
161	2012-09-05	Cessna 421B	USA	Fort Worth Spinks	/2	CEN12FA606	Shortly after takeoff, cargo door popped open, asym drag, crashed
162	2012-08-29	Beech 95-A55	USA	Millville, NJ	1/2	ERA12LA535	Simulating engine failure
163	2012-08-22	Cessna 421	Russia	Gorelovo	2/2	ASN	During touch and go, the right engine probably failed
164	2012-08-18	PA-34-200 Seneca I	Philippines	Cebu-Naga	3/4	PCI	Emergency landing due to engine problems. Crashed in sea.
165	2012-08-02	Beech E55 Baron	USA	Houston, TX	0/?	CEN12LA515	Rejected takeoff after loss of thrust left engine
166	2012-07-29	Piper PA-30	USA	Bragg City, MO	0/2	CEN12LA512	R. engine failed in-flight, forced landing in field
167	2012-07-27	Beech 95-A55	USA	Homerville, GA	0/1	ERA12LA503	Left engine failure in-flight, during forced landing collided with trees
168	2012-07-11	Piper PA-34 Seneca	AUS	Broome Apt	1/1	AO-2012-093	Likely left magnetos switched off, loss of speed and control; crashed
169	2012-06-30	Piper PA-31P	USA	Dalton, GA	1/1	ERA12FA423	R engine inop, left engine full power, collided with terrain



No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
170	2012-05-28	Diamond DA-42	Germany	Schwerin-Parchim	2/4	BFU CX009-12	R engine failure, prop not feathered, crashed
171	2012-05-17	ATR-72-212A	Germany	Munchen	0/62	FSF	RTB due to cabin smoke, #2 prop feathered, runway excursion
172	2012-04-21	PA-23-250 Aztec	Guatemala	Guatemala City	3/3	ASN	On takeoff, smoke left engine. Crashed.
173	2012-04-01	Beech 58	USA	Calhoun, KY	1/1	ERA12FA262	Left engine failure after takeoff. Loss of control, crashed.
174	2012-03-28	Beech E-55	USA	Broken Bow, NE	1/2	CEN12FA210	Single engine approach, crashed short of runway
175	2012-03-15	Convair 340	USA	San Juan, PR	2/2	DCA12FA051	Engine related emergency after takeoff, RTB, crashed on approach
176	2012-02-14	Beech G18	USA	Hollister, CA	0/2	WPR12LA104	During takeoff, right engine failure, closed throttles, landed hard
177	2012-01-13	Aero Commander 500-B	USA	Bartlesville, OK	0/1	CEN12LA134	During cruise, R engine surged, then left engine. Forced landing.
178	2011-12-22	Cessna 441	USA	Nashville, PA	1/1	ERA12FA120	On approach, probably right engine failure?
179	2011-12-26	Aero Commander 560-F	USA	Venice, FL	1/1	ERA12FA123	Loss power left engine after takeoff, crashed on final approach
180	2011-12-10	Beech 65-80 Queen Air	Philippines	Manila	3/3+11	BAAA-ACRO	Engine problems shortly after takeoff, crashed on a school
181	2011-12-09	Cessna 421C	USA	Sioux Falls, SD	4/4	CEN12FA100	Smoke left engine after takeoff, continued left turn, crashed
182	2011-12-02	Beech King Air C90	USA	Midland, TX		FSF	Engine problem final approach, struck house
183	2011-11-29	Cessna 402B	USA	Nantucket, MA	0/1	ERA12IA090	On short final, left engine failed. TD prior to runway, damaged
184	2011-11-12	Cessna 401A	USA	Gladewater, TX	0/5	CEN12LA061	After init go-around, roll to right; pwr reduced, landed. Eng fail?
185	2011-11-11	Beech 58	USA	Connersville, IN	0/2	CEN12CA062	During approach simulated right eng failure. Inpacted trees.
186	2011-10-27	Beech King Air 100	Canada	Vancouver, BC	2/9	A11P0149	On approach, increased thrust on one engine, lost control, crashed!
187	2011-09-12	Cessna 421C	USA	Sioux Falls, SD	4/4	CEN12FA100	Left engine failure, prop not feathered, stalled and crashed
188	2011-09-11	Piper PA-44-180	Belgium	Charleroi	0/3	AAIU-2011-23	Engine failure during go-around, probably due to carburetor icing
189	2011-08-21	Piper PA-31-310	USA	Cabazon, CA	0/3	WPR11LA401	Loss power #1, drifted down, forced landing in desert
190	2011-08-17	Cessna 310Q	USA	Tupelo, MS	1/1	ERA11FA458	After liftoff, at 300 – 500 ft left descending turn, crashed. Cause?
191	2011-08-09	Antonov 12A	Russia	Omsukchan	11/11	ASN	Engine fire en route, crashed
192	2011-07-11	Antonov 24RV	Russia	Strezhevoy	7/37	ASN	Eng. fire in-flight, crashed in river close to airport
193	2011-07-09	Cessna 421C	USA	Demopolis, AL	7/7	ERA11FA391	R eng. shutdown during cruise, diverted crashed close to airport,
194	2011-07-04	Cessna 421B	Bahamas	Mangrove Cay	0/1	A11-01314	R eng loss on takeoff, crashed 550 ft from departure end runway 27
195	2011-06-20	Cessna 402	USA	Caldwell, ID	0/8	WPR11LA269	R eng failed just after retracting gear; takeoff rejected
196	2011-05-21	Piper PA-30 or 40	USA	Philipsburg, OH	0/1	CEN11LA364	Loss of L eng. power during takeoff roll, veered off runway
197	2011-05-18	Saab SF-340A	Argentine	Prahuaniyeu	22/22	BAAA-ACRO	Engine problems en-route. Out of control, crashed
198	2011-04-10	Piper PA-34-200	Philippines	Plaridel Airport	3/6	RP-C5140	Right engine failure during takeoff, control lost, crashed
199	2011-04-02	Gulfstream GVI	USA	Roswell, NM	4/4	CEN11MA258	Takeoff with simulated engine failure
200	2011-04-01	Casa C-212	Canada	Saskatoon	1	FSA	R eng. power loss, SE appr, left eng lost power too 2nm from airport
201	2011-03-21	Antonov 12BP	Congo	Pointe Noir	21	FSA	Left side engines stopped on approach, rolled inverted, crashed
202	2011-03-16	Beech S. King Air 200	USA	Long Beach, CA	5/6	WPR11FA166	Reduced thrust left engine after takeoff, yawed, crashed. +overweight
203	2011-02-10	Fairchild SA227-BC Metro III	Ireland	Cork airport	6/12	AAIU 2014-001	
204	2010-12-23	Piper PA-30	Australia	Camden, NSW	-	AO-2010111	Forced landing during asymmetric flying training
205	2010-12-09	Beech 95	Brazil	BomJesus doGalho	4/4	ERA11WA089	Engine failure, impacted terrain
206	2010-12-09	Cessna 404	AUS	Mount Gordon, Q	0/9	AO-2010-105	Right engine failure and shut down on descent, landed safely
207	2010-12-04	Tupolev 154M	Russia	Moscow	2	FSA	Engines 1 and 3 flamed out during landing
208	2010-11-14	Piper PA-31-350	Australia	Marree (SA)	0/?	AO-2010-094	Engine failure during cruise, forced landing.
209	2010-11-11	Piper PA-44	USA	W- Palm Beach, FL	4/4	ERA11FA054	Left engine failure shortly after takeoff, crashed. Training flight
210	2010-11-05	Beech 1900C	Pakistan	Karachi	21/21	ASN	One min. after takeoff, one engine failed. Crashed while turning
211	2010-10-21	LET 410	Congo	Bugulumisa	2	FSA	Engine failure during climb out
212		Cessna 402C	Bahamas	Nassau	9/9	ERA11WA008	



No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
213	2010-09-22	Beech B100	Canada	Quebec	0/6	A10Q0162	While getting airborne, left engine lost power due to birds.
214	2010-09-19	Piper PA-31	Bahamas	South Bimini	0/6	Assoc. Press	Bagage door flung open, asymm drag, crashed in bushes
215	2010-09-13	ATR-72	Venezuela	Puerto Ordaz	17/51	KHOU.com	Problems one engine, emergency landing and crash
216	2010-09-10	Piper PA-310	Canada	Pickle Lake, Ont.	0/4	A10C0159	During cruise, left engine shut down. Lost alt., forced landing
217	2010-09-02	Beech 95	USA	Redwood City, CA	3/3	WPR10FA448	Maneuvers after TO similar to motions after R. engine failure. ?
218	2010-08-23	Piper PA-23 Aztec	USA	Bahamas	0/6	NDTV	Left engine failure after takeoff, crash landed in water
219	2010-08-10	Piper PA-44-180	USA	Eastman, GA	0/3	ERA10LA410	Left eng. fail during approach, R eng lost power as well, crashed
220	2010-07-27	Beech 95 55	USA	Oceanside, CA	1/1	WPR10FA369	After takoff, engines 'out of sync', at 50 ft right roll, crashed
221	2010-07-18	DHC6-300 Twin Otter	Indonesia	Bintunu Apt	0/9	NTSC	Right eng torque ind. failure at rotation, t/o aborted, veered to right
222	2010-06-23	Beechcraft A100 King Air	Canada	Quebec City	7/7	A10Q0098	Right engine problem after takeoff, no climb, cashed
223	2010-06-19	Douglas DC-3	Germany	Berlin	0/28	AircrashdB/FSA	After takeoff, left eng. failure, no alt gain, crash landed
224	2010-06-15	Piper PA-31P	Australia	Bankstown, NSW	2/2	ATSB	Eng. failure, crashed during returning to Bankstown
225	2010-04-20	Piper PA-44-180	USA	Tooele, UT	0/2	WPR10LA210	Eng fail during OEI training, forced landing
226	2010-04-11	Beech 95-A55	USA	Arecibo, PR	0/2	ERA10LA222	One engine failed in flight, pilot shut down other engine, forced land.
227	2010-04-07	Cessna 404	USA	Ponce, Puerto Rico	0/3	FRA10TA215	R. eng failure @200' after takeoff, no climb, forced landing
228	2010-04-01	Beech 95	USA	Eden Praire, MN	0/2	CEN10LA188	Loss engine power after takeoff, impacted terrain. 1 serious, 1 minor
229	2010-03-30	Antonov 74	Russia	Ivanovo	0	FSA	Aborted takeoff due to engine failure, overran runway
230	2010-03-28	Piper PA-30-160B	AUS	Jandakot, WA	2/2	AO-2010-023	Enroute Left prop feathered, R eng low RPM, crashed
231	2010-03-23	Piper PA-30	USA (AUS)	Hollister, CA	0	WPR10LA174	Engine failure during initial climb, crashed.
232	2010-03-22	Embraer 120ER	Australia	Darwin, NT	2/2	ASN	Takeoff, simulated engine failure, left roll, nose down, crashed
233	2010-03-18	AN-26B	Estonia	Talinn Airport	0/6	ASN	Go-around after engine failure
234	2010-03-05	Piper PA-34 -200T	USA	Vero Beach, FL	0/2	ERA10LA162	Practicing Simulated engine failure, crashed on approach
235	2010-02-17	Piper PA-30	USA	Amarillo, TX	2/2	CEN10FA122	After takeoff left prop feathered, crashed
236	2010-02-11	ATR-42-300	Indonesia	Tanjung Redep	0/56	ASN & ATSC	Engine failure during approach, 2nd engine during diversion
237	2010-01-28	GAF N22B Nomad	Philippines	Cotaboto-Awang	8/8	ASN	Engine fire/ failure during takeoff, crashed
238	2010-01-25	EMB-110C	Brazil	Porfirio Apt.	2/10	ASN	Engine failure during approach
239	2010-01-21	Beech 1900C	USA	Sand Point, AK	2/2	ANC10FA014	Engine failure and loss of control after takeoff, crashed in ocean
240	2010-01-18	Beech B-60	USA	Madison, AL	2/2	ERA10FA115	R. engine failure, impacted terrain.
241	2009-12-24	Piper PA-23-250	Bahamas	Plana Cays	2/2	A09-01502	Pilot reported Left engine problems; then both engines lost, ditched.
242	2009-12-18	Beech 95-B55	SA	Wonderboom	2/2	CA18/2/3/8725	On takeoff, R Eng fouled plug, not full power, Lost height, crashed.
243	2009-11-09	Beech B200	USA	Greer, SC	0/3	ERA10LA056	Engine failure during approach, out of fuel?
244	2009-11-05	G111 Albatross	USA	Fort Pierce FL	0/3	ASN	Nr. 1 engine failed on takeoff, crashed.
245	2009-11-04	Beech 95	USA	Brenham, TX	0/1	CEN10LA039	Eng fail shortly after departure, forced landing, subst. damaged
246	2009-10-22	BN-2 Islander	NL Antilles	Bonaire	1/10	PCI	#2 Eng fail on approach, ditched short of coast
247	2009-10-21	Boeing 707	UAE	Sharjar	6/6	PCI	After t/o, banked to right, crashed 3 km from airport. Eng fail?
248	2009-10-17	DC-3C Dakota	Phillipines	Manilla	4/4	RP-C550	After t/o, eng. problems, RTB, crashed
249	2009-09-24	BAe Jetstream 41	South Africa	Merebank	1/3	ASN	Eng. fail on t/o, crashed
250	2009-09-22	IL-76	Iran	Varamin	7/7	ASN	Eng. fire, vert. tail damaged, loss of control
251	2009-09-16	Piper PA-34 Seneca	Portugal	enroute	3/3	Paper	Eng. fail?
252	2009-09-16	Beech 200 Super King Air	USA	Hayward, CA	0/1	WPR09LA451	Loss power on t/o, crash landed off apt.
253	2009-08-21	Beech 58 (Ratheon)	USA	Teterboro, NJ	0/2	FRA09LA469	High speed appr. Eng Failure?
254	2009-08-14	Beech 99 (F)	Portugal	Évora	2/2	CEN09WA524	LEI, go-around, turned left and collided with building
255	2009-07-18	Beech TC-45J	USA	Verdel, NE	1/2	CEN09LA444	Loss eng pwr, forced landing, pilot not twin rated



No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
256	2009-07-05	BN-2 Trislander	New Zealand	Gt Barrier Isl.	0/11	FSF	#3 prop separated
257	2009-07-04	BN-2 Islander	Guyana	Baganara Isl.	0/10	FSF	Eng. inop, emer landing, minor a/c damage
258	2009-07-03	Piper PA-34-200T	Brazil	Imperatrize, Mara.	0/2	ERA09WA406	OEI after t/o, forced landing landed short of rwy 25
259	2009-07-03	Piper PA-30 Twin Coman.	USA	Tucson, Az	0/4	WPR09LA324	Loss left eng pwr during t/o, impacted ground
260	2009-06-24	Beech 95	USA	Holbrook, AZ	4/4	WPR09FA309	Eng fail? after t/o. cont. roll to left.
261	2009-05-14	Piper PA -23 Aztec	Guatemala	La Aurora	6/6	CEN09WA306	Eng fail? Destroyed shortly after t/o
262	2009-03-09	PZLM28TDBryza2RF	Polen	Gdynia	4/4	ASN	Crashed during training SE approach & landing
263	2009-03-06	NAL Saras	India	Bidadi	3/3	ASN	Crashed during engine off test
264	2009-03-09	Ilyushin 76T	Uganda	Lake Victoria	11/11	PCI	Loss of engine power, crashed.
265	2009-03-06	N-22B Nomad	Thailand	Lop Buri Air Base	1/5	ASN	Eng problems after t/o, crashed.
266	2009-02-07	EMB 110 P1	Brazil	Santo Antonio	24/28	ASN	Eng. failure after takeoff, crashed in river
267	2009-01-29	Cessna 421B	Bahamas	Nassau	0/12	A0929630	OEI on appr. a/c subst, damaged
268	2009-01-17	Beech 58 Baron	SA	Thabazimbi	0/6	CA18/2/3/8605	R. Eng shut dn, loss of control, rapid descent, crashed
269	2008-12-18	Piper PA-31T Cheyenne	Argentina	Tigre	2/2	ASN	Tech problems after t/o, RTB, crashed (Eng fail?)
270	2008-12-15	BN-2A Trislander	Dom. Rep.	Santiago	12/12	PCI	Mayday call, crashed – eng. fail?
271	2008-12-09	MU-2B	USA	Millington, TN	0/1	ERA09FA083	Eng fail, RTB. Veered off runway
272	2008-11-28	Beech 58 Baron	Brazil	Anápolis	4/6	ASN	Loss of control after t/o, crashed on rwy. Eng fail?
273	2008-11-23	Beech 200 Super King Air	Brazil	Recife – PE	2/10	ASN	Out of fuel on appr. (asym thrust?)
274	2008-11-13	AN-12	Irak	Bagdad	7/7	PCI	A/c malf. shortly after t/o. Eng. fail?
275	2008-11-03	Beech 200	Mexico	Punto Chivato	1/1	CEN09WA052	Lost a/c + ROC – stall? impact gnd Engine failure?
276	2008-11-01	CASA 212	USA	Toksook Bay, AK	0	ANC09LA009	Engine failed on appr, no auto fth, GA, emer landing, 2 injured
277	2008-10-24	Cessna 402C	Paraguay	Asuncion	5/5	ASN	Crashed after t/o, maint. test flight. Eng fail?
278	2008-10-23	Beech 58 Baron	South Africa	Limpopo	1/1	CA 18/2/3/8568	After t/o, R Eng failure, crashed
279	2008-10-21	Cessna 310	Mexico	Pedro J/ Mendez	5/5	ASN	Loss pwr during t/o, crashed
280	2008-10-06	Cessna 421	Mexico	Oaxaca	2/2	CEN09WA016	R Engine fail, RTB, loss control while performing 360
281	2008-09-20	Piper PA-34-220T Seneca	Mozambique	Beira	6/6	ASN	OE stopped, crashed during emer landing
282	2008-09-02	Lockheed Neptune	USA	Reno, NV	3/3	ASN	Loss pwr left, loss of control after t/o
283	2008-08-28	Piper PA-31-350 Navajo	USA	Las Vegas, NV	1/1	ASN	Reported rough engine, RTB, crashed
284	2008-08-25	Beech 55 Baron	Chile	Coricó Apt	3/3	ASN	Eng fail reported by pilot (prelim. info)
285	2008-08-24	B737-219	Kyrgyzstan	Bishkek	68/90	AD + PCI	Eng failure after t/o, RTB, crashed, fire.
286	2008-08-22	Beech A100 King Air	USA	TusherCanyon	10/10	ASN	Emer landing in desert, Eng Fail?
287	2008-08-04	Piper PA-31Chieftain	USA	Aniak, AK		ANC08LA097	At 200' engine failure, landed
288	2008-08-03	Beech 65-A90	Canada	Pitt Meadows Apt	0/7	A08P0242	Left engine failed, wrong engine shut down, forced landing
289	2008-08-01	Piper PA-44-180 Seminole	Croatia	Zadar	2/2	BFU 4X029-08	D-GZXB, Vmca training, lost control, spin, crashed in sea
290	2008-07-25	Piper PA-31-350	Australia	Darwin			Landed on taxiway
291	2008-07-23	F-27-400M	Bolivia	Beni	0	ASN	#1 inop enroute, forced landing on road
292	2008-07-10	Beech 99A	Chile	Puerto Monz	9/9	PCI	After t/o, sharp turn left, crashed. Eng. fail?
293	2008-07-16	DHC-6	Canada			FSF	?
294	2008-07-07	B747-209B(SF)	Colombia	Mosquera Bogota	0/8+3	AD	Engine failure after t/o, RTB, crashed in field
295	2008-06-30	IL-76TD	Sudan	Khartoum	4/4	AWST 7-7-08	Engine fire after takeoff
296	2008-06-29	Beech 95 Travel Air	USA	Jasper, AL	4	NYC08FA231	Engine failue during t/o
297	2008-06-20	SA-226T Merlin IIIB	Norway	Bergen	3/3	ASN	A/c missing during training flight. Eng inop?
298	2008-05-29	PA-23-250 Aztec	SA	Wonderboom	0/1	CA 18/2/3/8504	At liftoff, R Eng stopped, lost control, crashed



No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
299	2008-05-02	Beech 1900C	Sudan	Rumbek	24/24	PCI	Eng. problems, crashed
300	2008-04-29	Cessna 310	Spain	Carabachel	2/2	ASN	Training flight, lost control, crashed. Eng inop?
301	2008-04-28	Piper PA-31-310 Navajo	Venezuela	Catia La Mar	3/3	NYC08WA173	Engine failure after t/o, struck building, fire
302	2008-04-25	BE-C50 Twin Bonanza	Philippines	Roxas Palawan		RP-C1950	OEI go-around, landed gears up in grass
303	2008-04-25	Cessna 421	Mexico	Saltillo Plan	0/6	ASN	Engine failure, crashed, burned
304	2008-04-21	EMB-110	Brazil	Coari Apt	0/14	ASN	Eng fail en route, slid off rwy on landing
305	2008-04-15	Piper PA-23-160 Apache	USA	San Dimas, CA	0/2	ASN	Loss control after t/o. Left eng fail power loss
306	2008-04-12	Cessna 310Q	USA	Compton, CA	0/2	ASN	Loss eng. pwr on final approach
307	2008-04-11	AN-32	Moldova	Chrisinau	8/8	PCI	Eng. problems, RTB, crashed on landing
308	2008-04-02	Beech 95-B55	USA	Benson, AZ	2/2	LAX08FA092	Bounced hard, GA, flipped over, suspect left engfailure
309	2008-04-01	Let 410 UVP E3	Venezuela	Les Roques	18/18	PCI	Eng. failure – crashed in sea
310	2008-03-21	Beech 76	USA	Rome, GA	2/2	NYC08FA143	Engine inop training flight
311	2008-03-15	Beech 1900	Nigeria			FSF	?
312	2008-02-28	Piper PA-34-200 Seneca	Chile	Lago Ranco	3/6	ASN	Crash after t/o, possible eng failure
313	2008-02-20	Beech 95-55	France	Auxerre	1/2	FR/ ASN	Engine failure, impacted terrain
314	2008-02-11	Cessna 310N	Iceland	Atlantic	1/1	CHI08FAMS1	Eng. pwr loss during ferry, ditched, not found.
315	2008-02-07	BN-2A-26 Islander	Dom. Rep.	El Seibo	0	ASN	Crash landed following engine failure
316	2008-01-23	Beech 58P	UK	Guernsey	2/3	ASN	Left engine failure, ditched near Cherbourg
317	2008-01-05	Piper PA-31-350	USA	Kodiak, AK	6/10	ANC08MA038	Open bag. door, asym drag, ditched
318	2008-01-04	LET 410 UVP-E3	Venezuela	Los Roques	18/18	PCI	Engine problems reported, crashed in sea while en-route
319	2007-12-30	N-22B Nomad	Indonesia	Sabang	5/7	ASN	Eng problems after 15 min , RTB, ditched
320	2007-11-08	AN-12	Sudan	Khartoum	0/4+2	PCI	At t/o, eng. fail, RTB, crashed
321	2007-10-17	BN-2A-21 Islander	Spain	Guadalcanal	1/2	ASN	After t/o, #2 loss pwr, pwr restored, hit hill
322	2007-10-11	Beech 200 Super KA	Colombia	Bogota	7/7	ASN	Emer after t/o, RTB, crashed. Eng fail?
323	2007-10-04	AN-26	Congo	Kinshasa	21/22	PCI	Crashed after t/o, eng. fail?
324	2007-09-26	Cessna F406	Uganda	Entebbe	2/2	ASN	Collided with ground after t/o, eng fail?
325	2007-09-03	Beech 58	USA	Munster, IN	2/2	ASN	Fuel starv. left eng at appr., loss of control
326	2007-08-26	AN-32	Congo	Kongolo	14/15	ASN	Engine failure 10 mins after t/o. RTB, crashed
327	2007-08-25	Piper PA-39	France	Vannes	2/2	ASN	Loss control at departure, eng. fail?
328	2007-08-22	EMB 110P1 Bandeirant	Brazil	Curitiba	2/2	ASN	Engine failure. Crashed shortly after takeoff
329	2007-08-09	DHC-6 Twin Otter	Fr Polynesia	Moorea	20/20	NTSB interim	Impacted water shortly after t/o, Engine failure?
330	2007-07-31	DC-3 Dakota	Colombia	San Jose d G	-	ASN	Engine failure, emer landing in rice field
331	2007-07-29	AN-12BP	Rusland	Moscow Airport	7	ASN	#4 then #3 auto fth on t/o
332	2007-07-23	AN-26	Ethiopia	Dire Dawa	1/9	PCI	Engine failure after t/o – crashed during RTB
333		Piper PA-31-350	Canada	Matheson Isl, Manit	0/8	A07C0119	After liftoff, R eng power loss, no climb perf., forced landing
334	2007-07-09	Piper PA-30 Twin Coman.	USA	Nichols, FL	2/2	ASN	Eng fail at t/o, crashed
335	2007-07-08	DHC-6 Twin Otter	Canada	Muncho Lake	1/5	ASN	Crashed shortly after t/o. Engine failure?
336	2007-06-21	Let 410	Congo	Kamina	1/25	ASN	Crashed shortly after t/o. Engine failure?
337	2007-05-17	Let 410 UVP	Congo	Walikale	3/3	PCI	Eng. fire after t/o, RTB, crashed
338		Piper PA-34 200T	Malawi	Kamuzu	2/2	SA CAA	Descended continuous left turn until impact. Eng. failure??
339	2007-03-04	Beech 95-C55	USA	Port Orange, FL	1/1	MIA07FA056	Fuel starvation left eng at t/o, lost control
340	2007-02-16	Piper PA-34-200T	Brazil	Fernando de N	1/1	ASN	R eng problem, crashed
341	2007-02-07	BN-2A-21 Islander	Philippines	Suba-Basbas	6/6	ASN	Engine vibrations on appr, ditched



No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
342	2007-02-04	Piper PA-30 Twin Coman.	Australia	Gold Coast Airpt	1/1	200700358	R. engine failure, then L. eng fail, crashed in water
343	2007-01-08	Piper Aerostar 601P	USA	NY		FSF	Eng fuel starvation ?
344	2006-12-19	Piper PA-34-220T	Germany	Friedrichshafen	0	CX 021-0/06	GA, loss R engine power, t/o aborted
345	2006-12-02	Partenavia P68B	Nw Zealand	Waipukurau	-	06-006	Fuel starvation, emergency land OK, procedures!
346	2006-11-27	AN-74T	Iran	Tehran	38/38	PCI	Engine failure during t/o, crashed
347	2006-11-10	BN-2T Turbine Isl.	India	Veloor	0	ASN	Lost eng power, crash landed in a marsh
348	2006-11-09	Let 410UVP	Congo	Walikale	0	ASN	Engine failure, RTB, emerg landing, written off
349	2006-10-29	B737-200	Nigeria	Abuja	97		Crash shortly after t/o
350	2006-10-18	Beech 90	France	Besancon			Impact terrain t/o, BFU investigates
351	2006-10-03	MU-2B-25	USA	Hillsboro	4	SEA05FA105	Pilot failed to obtain Vmca
352	2006-09-20	Saab SF-340	Australia		0		Left Engine failure, RTB OK
353	2006-08-28	N-22B Nomad	Argentina	Cerrillos	0	ASN	Engine problem descent, forced landing plowed field
354	2006-07-29	DHC-6 Twin Otter	USA	Sullivan, MI	6/8	CHI06FA210	Engine failure t/o, skydiver flight
355	2006-07-19	DC-3 Dakota	USA	St Thomas, VI	0	MIA06LA125	Power loss - ditching
356	2006-07-18	Beech 58P Baron	USA	Jeanerette, LA	2+1	DFW06FA186	Loss of control, GA, No engine failure, cause?
357	2006-07-11	Piper PA-34-200T Seneca	Canada	Edson, Alberta	1/1	A06W0111	Left engine failure, crashed on short final
358	2006-07-10	F-27-200	Pakistan	Multan	45/45	ASN + PCI	Engine failure t/o, crashed
359	2006-07-07	AN-12B	Congo	Sake	6/6	ASN	Engine failure en-route, crashed into hill
360	2006-07-07	AN-12B	Congo		5		Engine failure
361	2006-06-25	MU-2B-60	USA	Fort Pierce, FL	1/1	MIA06FA120	LOC during initial climb because of sudden loss of thrust R. engine
362	2006-06-09	Piper PA-44-180	Australia	Pacific Ocean	0	200603333	AUS a/c, ditched after Engine failure
363	2006-05-14	CV-580	Canada	La Ronge	1/3	A06C0062 p?	Engine failure during GA
364	2006-03-23	AN-24B	Iraq	Talil	0	ASN	Engine failure @ descent, forced landing unpaved field
365	2006-03-08	Cessna 414	USA	Kahului, HI	3	LAX06FA126	Engine failure (reduced RPM) on approach
366	2006-02-08	Swearingen SA226 Metro	USA	Paris, TN	1/1	PCI	Asymm fuel, descend – mayday - crashed
367	2006-02-03	Beech 200	USA	Myrtle Beach, SC	6	ATL06FA044	L throttle stuck? poss eng shutdown during next app
368	2006-01-19	Beech 58P Baron	Australia	McArthur rvr		200600256	Engine failure?
369	2006-01-08	AN-12	Uganda	Bukalaza	6/6	PCI	Engine failure, overweight, improper balance
370	2006-01-01	Piper PA-30 Twin Coman.	Australia			200604360	Engine failure, then TEI
371	2006-01-01	Piper PA-31-350	Australia			200606530	Engine problems?
372		AN-28	Sudan		2/2		Crashed shortly after t/o
373	2005-12-23	AN-140-100	Azerbaijan		23/23		Crashed shortly after t/o
374	2005-12-20	MU-2B-36	Canada	Terrace	2/2	NYC06WA046	+ CA A05P0298 L Eng fail shortly after t/o, no feather, crashed
375		C-130B Hercules	Iran	Tehran	94/94	AD	Engine 4 failure after t/o, RTB, lost control, crashed
376		Piper PA-23-250	USA	Turks & Caicos Isl	4	MIA06WA035	Engine failure? Crashed shortly after t/o
377		BN-2A-21	Belize		-		?
378		Piper PA-31-350	USA	Ankeny, IA	2	CHI06FA026	RTB with engine problem
379	2005-11-04	Beech 95-55	Venezuela	Santiago	1		Engine failure
380	2005-10-23	Cessna 411	USA	East Hampton NY	1	NYC06FA015	Left engine failure en-route, crashed at dest.
381	2005-10-22	B737-200	Nigeria	į ir			t/o
382	2005-10-22	Piper PA-38-112	UK	Biggin Hill	2/2		?
383	2005-08-06	ATR-72-202	Italy	Palermo	11/39	AD	Engine problem on departure, RTB, ditched
384		AN-24B	Eq. Guinea	Baney	60/60	PCI	Eng. fire after t/o, crashed, was overloaded




No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
385	2005-06-13	DC-3 variant	USA	Ft Lauderdale	0	AD	Engine #1 fire after t/o, clipped houses, crashed, fire
386	2005-06-05	AN-24B	Sudan		3/42		Fire I eng. Belly land
387	2005-05-24	MU-2B	USA	Hillsboro, OR	4	SEA05FA105	Part. power loss L engine, loss of control, t/o
388	2005-05-05	AN-24	Congo	·	10/11		?
389	2005-04-22	Piper PA-31-350	Canada	Comox, BC	2/2	A05P0080	R. eng fire on approach, no feather, rolled inverted, crashed
390	2005-03-26	Let 410 UVP-E	Colombia	El Embrujo	8/14		Lost control shortly after t/o, crashed. Eng. fail?
391	2005-03-06	B737-200	Algeria	Tamanrasset	100+		Engine failure t/o
392	2005-03-05	IL-76TD	Tanzania		8/8		Shortly after t/o
393	2005-01-08	AN-12	Uganda		6/6		Cg + engine failure after t/o
394	2004-12-10	MU-2B-60	USA	Englewood	2	DEN05FA034	Left engine shutdown, loss of control during approach.
395	2004-12-04	CV-340	USA	Opa Locka	0	AD	Engine failure after dep. no fth poss, ditched
396	2004-12-04	CV-340-70	USA	Miami	0/2	ASN	Smoke #1, unable to fth, lost alt. ditched
397	2004-11-17	Let 410UVP-E20	Tanzania	Kilimanjaro airp	0/2	ASN	Training flight, SE overshoot, lost control, crashed
398	2004-11-03	Piper PA-23-250 Aztec	Bahamas	Nassau	0/3	8 Dec 2004	R engine failure on approach, hit power line during off-field landing
399	2004-10-22	Beech 1900C	Bahamas	New Providence	0/?	A0514022	Right engine stopped from fuel starvation
400	2004-10-05	AN-12	Sudan	Kadukli	4/4	ASN	Engine failure, diverted, crashed
401	2004-10-01	EMB 110P1 Bandeir.	Cameroon	Douala Airport	0/4	ASN	Lost control on t/o when #1 failed
402	2004-09-30	Beech 95A	USA	Burlington	3	CHI04FA290	R engine failure
403	2004-09-10	SA 227AC Metro III	South Africa	George	0	ASN	R Engine failed on appr, GA, aborted, ext damage
404	2004-09-01	Piper PA-31	Spain		3	NYC04WA203	?
405	2004-08-25	B777-312	Australia	Melbourne	0		Engine failure @ V1 - uneventful
406	2004-08-13	CV-580	USA	Hebron, KT	1/2	AD	Low power on app, crash landed on golf course
407	2004-07-12	CV-440	Virgin Isl.	ernroute to St M	1/2	ASN	Engine failure en-route, eng fire – fell off, ditched
408	2004-06-26	Lisunov Li-2T	Russia	Moskva	2/5	ASN	Eng. failure after t/o, lost alt., crashed against building
409	2004-06-26	AN-12BP	Sudan	Wau airport	0	ASN	Bird strike, #3&4 out, emerg landing in a field
410	2004-06-20	DC-3 Dakota	Colombia				?
411	2004-06-20	DC-3 Dakota	Colombia	Las Gaviotas	0	ASN	R engine failure at liftoff + on fire. Crash landed
412	2004-06-08	HS-748-232	Gabon	Libreville	19/30	AD	After t/o, eng. fail, RTB, Ditched.
413	2004-06-04	Li-2T	Russia		2/5		Power loss one engine
414	2004-05-18	IL-76TD	China		7/7		Lost height on t/o, crash
415	2004-02-10	F27 Mk 050	UAE	Sjarjah	43/46	ASN	During approach, left prop to full reverse, right pos.pitch, LOC, crash
416	2003-11-11	Piper PA-34-200 Seneca	Australia	Bankstone	2/2	200304589	Engine failure during GA during multi-engine training
417	2003-11-08	Shorts SC-7 Skyvan	Guyana	Ogle	2/7	PCI	R. eng fail 1 min after t/o, forced landing
418	2003-10-26	FH-227B	Argentina	Buenes Aires	05/5	AD	RTB after t/o, Engine failure?
419	2003-10-01	Piper PA-23-250 Aztec	Australia	Mareeba		BO/200304091	Left engine failure
420	2003-08-26	Beech 1900D	USA	Hyannis, Ma	2/2	AD	Engine failure after t/o?
421	2003-08-24	LET 420UVP-E	Haiti	Cap Haitien	21/21	PCI	Shortly after t/o smoke, uncontrolled dive, crashed
422	2003-08-11	Cessna 404	Australia	Jandakot		200303579	Engine failure
423	2003-07-13	Cessna 402C	Bahamas	Treasure Cay	2/10		D3 Eng. failure en route, ditched lack of performance
424	2003-07-08	B737-200C	Sudan	Pot Sudan	116/127	WAS03RA019	Engine failure 10 min after t/o, RTB, GA, crashed
425	2003-06-30	C-130H	Algeria	Blida	4/4	PCI	Eng. fire after t/o, crashed
426	2003-06-26	Cessna 414	USA	N. Ft. Myers, FL	2/4	MIA03FA135	Engine failure on final, no fth
427	2003-06-16	Piper PA-31P	USA	Augusta, GA	2/2	ATL03FA107	Engine problem after t/o



No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
428	2003-06-11	EMB-820C Navajo	Brazil	Belo Horizonte	4/4	PCI	Low oil press., RTB, crashed on approach
429	2003-05-18	Piper PA-31 Navajo	Barbados		2/2	AAIB 11/2003	Lost one engine, ditched
430	2003-03-06	B737-200	Algeria	Tamanrasset	102/103	7t-z030306a	Engine failure after V1, crash
431	2003-02-10	AN-28	Finland	Tallinn	2/3	PCI	Eng. fail after t/o, crashed
432	2003-02-07	Beech 76 Duchess	Australia	Camden, Aero	1/2	200300224	Engine failure during training
433	2002-12-26	EMB-110 Bandeirante	Brazil	Curitiba	3/16	PCI	Eng. trouble enroute, diverted, crashed
434	2002-12-17	Piper PA-31 Navajo	New Zealand	Feilding	3	02-015	Engine failure t/o, RTB, Left Eng. failure approach
435	2002-11-28	LET 410 UVP-E20	Kenya	Enroute	1/20	PCI	Eng fail enroute, crashed
436	2002-11-11	F-27-600	Philippines	Manila	19/34	AD	L. Engine failure shortly after t/o, ditched
437	2002-11-07	BN-2A-21	Indonesia	Tarakau	7/10	PCI	Eng fail 2 min after t/o, RTB, crashed
438	2002-08-14	Piper PA-44-180	Netherlands	Kampen	3	2002124	Engine failure during training, wrong fuel sel. closed
439	2002-07-04	Cessna 310	USA	CA	2/2	PCI	Power loss at t/o, left bank, crashed
440	2002-05-25	B747-200	Taiwan	Makung Island	206	DCA02RA038	China airl. CI-611. Engine failure?. Invest. by Taiwan
441	2002-05-15	Partenavia P68B	New Zealand	Wairoa	0	02-006	Power loss
442	2002-05-04	BAC 1-11 525FT	Nigeria	Kano	74/77+75	AD	Engine problems after t/o, crashed in populated area
443	2002-04-15	MU-2B-35	Puerto Rico	Carolina	1/1 +1	MIA02FA084	Orbiting for approach, engines cutting in & out
444	2002-02-19	Cessna 421	France	Artigues de L			?
445	2001-11-27	Beech C90	Australia	Toowoomba	4	200105618	+ sup + 20050707 Eng failure shortly after t/o
446	2001-11-12	Airbus A300B4-605R	USA	New York, NY	260/260+5	AD	Fire Engine #1, engine separated, vert. tail separated
447	2001-09-18	Let 410UVP-E	Guatemala	Guatemala City	8/13	AD	Engine problems after t/o, crashed
448	2001-09-18	LET 410UVP-E	Guatemala	Guatemala City	9/13	PCI	At t/o, eng. fail, crashed
449	2001-08-29	CASA 235-200	Spain	Malaga	4/47	AD	Engine failure on approach, crashed short of runway
450	2001-07-12	AN-28	Venezuela	Puerto Cabello	13/13	PCI	R. eng fail after t/o, crashed
451	2001-06-15	Transall C-160NG	Indonesia	Jayapura	1/19	PCI	Eng. trouble, RTB, skidded off runway
452	2001-06-11	Piper PA-34-200T	Germany	Thyrnau	0, 5w	3X114-0/01	Engine failure en-route, emerg landing, too heavy
453	2001-05-17	F-27 400M	Argentina	Mendoza	5/5	AD	After t/o #2 failed, r. turn, crashed
454	2001-05-01	MU-2B	USA	TheWoodlandsTX	2	FTW01FA111	Engine failure, out of control
455	2001-03-24	DHC-6 Twin Otter	France	St Barthelemy		F-ES101324	Use of Beta range in-flight
456	2001-01-25	DC-3C	Venezuela	Ciudad Bolivar	24/24	PCI	Fire after t/o, rolled inverted, crashed
457	2001-01-24	Beech F90-42	USA	Nashville, TN	4/4	ATL01FA027	Engine failure (R) shortly after takeoff, crashed
458	2001-01-17	Beech 95-D55	Germany	Rendsburg	0	3X006-0/01	Engine failure during climb, spiral.
459	2000-11-15	AN-26	Angola	Luanda	57/57	PCI	Eng. fail after t/o, crashed
460	2000-11-01	DHC-6 Twin Otter	Canada	Vancouver Harb.	0/?	A00P0210	On takeoff, R. engine failure at 50 – 100 ft, ditched
461	2000-09-29	Piper PA-34 200T	New Zealand	Gisborn	0/1	CAA #00/3191	Engine failure on left base, ditched
462	2000-08-25	Piper PA-31 Chieftain	USA	Hawaii	1/9	PCI	R. Eng failure, ditched
463	2000-07-25	Concorde	France	Paris, Gonesse	109/109+5		Fire left side, # 1 & 2 failed after t/o, loss of control, crashed
464	2000-07-20	DC-3 Dakota	Bahamas	Nassau	2/2	AD, PCI	After t/o, Eng #2 failed, RTB, crashed
465	2000-07-19	g-159	usa	Linneus, M	2/2	PCI	Eng power loss, V < Vmca, crashed
466	2000-07-09	Curtis C-46A	Colombia	Villavincencio	13/19	DCA00WA067	Engine failure at t/o
467	2000-07-02	N-22C	Philippines	Cagayaacillo	14/15	PCI	Eng. problem, RTB, overran, ditched
468	2000-05-31	Piper PA-31	Australia	Adelaide	8/8	FSF publ	Loss eng power, left first, then right as well
469	2000-05-21	BAe Jetstream 3101	USA	Wilkes-Barre	19/19	DCA00MA052	Engine failure + fuel shortage
470	2000-05-21	Bae Jetstream 3101-31	USA	Wilkes Barre, P	19/19	PCI	Eng fail, low on fuel, out of control



No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
471	2000-03-30	AN-26	Sri Lanka	Anuradhapura	40/40	AD	Crashed 10 min after reporting engine trouble
472	2000-02-13	Beech 1900D	Australia	Williamtown		BO/200000492	Training incident Engine failure
473	2000-01-22	MU-2B-26A	USA	San Antonia, TX	2/2	FTW00FA070	Loss of R. engine power during initial takeoff, crashed
474	1999-12-06	Piper PA-31-350	South Africa	Johannesburg	9/9	PCI	Eng. fail at t/o, crashed
475	1999-09-03	Cessna 404 Titan	UK	Glasgow	8/11	2-2001 G-ILGW	Engine failure, other prop feathered, crashed out of control
476	1999-07-04	DC-6A	Colombia	Villavicencio	5/18	PCI	Eng. fail at t/o, RTB, crashed
477	1999-06-29	Beech 58 Baron	USA	Atlanta, GA	2/2	ASN	Engine problem shortly after takeoff, one engine out, LOC, crashed
478	1999-02-08	L-188A Electra	Congo	Kinshasa	7/7	PCI	At t/o, #3 failed, RTB, crashed
479	1999-02-02	AN-12	Angola	Luanda	14/14	PCI	Eng. trouble, crashed
480	1999-01-16	BN-2A	Australia	Coconut Isl.	3/4	PCI	L. eng fail during GA, loss of control
481	1998-07-29	EMB 110	Brazil	Manacapuru Rvr	5/24	PCI	Eng problem, ditched in river
482	1998-07-28	SA-227AC	Spain	Barcelona	2/2	PCI	R. eng. inop for training, crashed
483	1998-06-18	SA-226TC	Canada	Montreal	11/11	PCI	Fire left eng., wing failed on landing
484	1998-06-08	BN-2A Trislander	UK	New Jersey	0		Engine failure – no climb performance left
485	1998-03-31	CV-240-53	Mexico	Mexici City	2/4	PCI	Fire eng. 2, crashed
486	1998-03-28	AN-32	Peru	Piuara	22/55	PCI	Eng. fail, crashed
487	1998-03-18	Saab SF-340B	Taiwan	Hsinchu	13/13	PCI	Loss power #2, crashed
488	1998-02-04	AN-12BP	Portugal	Terceira	7/7	PCI	After t/o, loss power #3 & 4, crashed
489	1998-01-27	F27-600	Myanmar	Yangou	16/45	PCI	#2 failed on t/o, swerved off runway
490	1997-12-13	SA-226T Metro II	Bolivia	La Veriente	10/19	PCI	After t/o, eng. fail, auto feather, rolled, crashed
491	1997-12-04	PA-34	USA		0/1	CHI98LA054	Inadvertent switched off left magnetos, crashed
492	1997-07-17	F-27-600	Indonesia	Bandung	30/50	PCI	L. eng fire after t/o, crashed during emer landing
493	1997-07-11	AN-24	Cuba	Havana	44/44	PCI	L. eng. failed on t/o, crashed
494	1979-05-25	DC-10	USA	Chicago	271+	ASN	Flight 191 #1 engine dropped off wing
495	1997-04-19	BAe ATP	Indonesia	Tanjung Tadan	15/53	PCI	Eng. fail on approach, GA – crashed
496	1997-04-04	ATL-98 Carvair	USA	Griffin, GA	2/2	PCI	Eng. fail on t/o, overran, crashed in building
497	1997-03-13	C-130HF	Iran	Mashad	88/88	PCI	Eng fail, crashed
498	1997-02-01	HS-748	Senegal	Tambacoumba	25/52	PCI	Pwr loss left eng, after t/o, crashed
499	1997-01-27	DHC-4A Caribou	USA	Sparrevohn	1/2	PCI	Eng. trouble en-route, crashed on full power
500	1996-12-24	HAL 748-2	India	Nellore	22/22	PCI	Eng. fire, crashed en-route
501	1996-12-16	PA-34-200T	USA	Birmingham, Al	3/3	MIA97FA040	L eng not full power after t/o, RTB, crashed, prop not feathered
502	1996-12-09	DC-3	USA	Boise, ID	2/2	PCI	After t/o, R. eng. fire, RTB, V <vmca, crashed<="" td=""></vmca,>
503	1996-12-07	Casa 212	Indonesia	Banjarmasin	16/17	PCI	Fire #2, RTB, crashed short of runway
504		C-130P	USA	Cape Mendo, CA	10/11	PCI	Eng failure, then complete elec fail, crashed
505		Cessna 421C	FR	Aubusson	8/8	PCI	Eng. failure at decent, no feather, crashed
506	1996-10-22	Boeing 707	Ecuador	Manta	4/4	PCI	Eng. fire after t/o, crashed
507	1996-10-20	PA-31-350	Canada	Nw Brunswick	8/8	PCI	Loss of power R. engine, crashed
508	1996-10-31	Fokker 100	Brazil	São Paulo	96/96	ASN	Right reverser deployed at takeoff, yawing moment increased to max.
509	1996-09-25	DC-3 Dakota	Netherlands	Waddenzee	32/32	ASN	#1 failed after t/o unable to fth, V <vs, ditched<="" td=""></vs,>
510		DC-4	Canada	Bronson Creek	1/3	PCI	After t/o, out of control, landed in river
511	1996-07-15	C-130H	Netherlands	Eindhoven	34/41	PCI	Loss of control at GA, eng.3 shut down, 1&2 quit after bird hit
512	1996-05-11	Piper PA-30 Twin Coman.	,			?	#1 fail G-ASYK
513		DH-104 Dove	Australia	<u> </u>	+		Engine failure





No.	Date (y-m-d)	Airplane type	Country	Location	Fatal/POB	Report No. 1)	Brief description (? = not confirmed by report yet)
514	1996-02-12	N-24A Nomad	Haiti	Port-au-Prince	11/15	PCI	Engine failure at liftoff
515	1996-02-04	DC-8-55F	Paraguay	Asuncion	4/4+24	PCI	Pwr loss 2 engines, lost control, crashed on soccer field
516	1996-01-08	BN-2A-27 Islander	Barbados	Bridgetown	1/10	PCI	Eng. fail, lost alt., ditched